

Screen 0% Outdoor F.R.























P/807-300



Ref.	 cm	 mm	 g/m ²																	
	cm	mm	g/m ²	Composition	Flame retardant	Transparency	Health certification	IMO - Fabrics for marine industry	Solar reflection	Solar absorption	Openess factor	Colour fastness	Light transmission	Light absorption	Sound absorption	G tot Type C - GLASS	G tot Type C - GLASS	WARP	WEFT	
P/807-300	300	0,90	764	22% PL 78% PVC	Classe1 (I);B1 (D);NFPA701 (US); BS (GB)	Blackout	FUNGISTATIC, GREENGUARD GOLD, OEKO-TEX	8	heat	No	0.00	0	4	96	4	0,56	0,09	100	350	120

All coefficients have a possible tolerance of +/- 5%
Attention: colour shades may vary slightly from one dye lot to another

	Width		Composition		Health certification		IMO - Fabrics for marine industry		Solar reflection		Light absorption		Sound absorption
	Thickness		Flame retardant		Colour fastness		Openess factor		Solar absorption		G tot Type C - GLASS		Warp - Weft N5 cm
	Weight		Transparency		Sealable		Solar transmission		Light transmission		UV reduction		

MAINTENANCE HANDLE THE FABRIC WITH CARE, USING CLEAN DRY HANDS. DO NOT USE SOLVENTS OR ANY ABRASIVE SUBSTANCES THAT MAY DAMAGE THE FABRIC. WHEN CLEANING WINDOWS THE BLIND MUST BE RAISED TO AVOID ANY DIRECT OR INDIRECT SPRAY OF CLEANING PRODUCTS. REMOVE THE DUST WITH A VACUUM CLEANER OR USING COMPRESSED AIR, AVOID PULLING OR STRETCHING FABRIC. ONLY FOR PVC COATED PRODUCTS, CLEAN WITH A DAMP CLOTH OR A SPONGE DIPPED IN SOAPY WATER IF NECESSARY. RINSE WITH CLEAN WATER. DO NOT RUB. LEAVE THE BLIND DOWN UNTIL COMPLETELY DRY.